

Inspection Photos
Location Name: Champlin 248 Amoco C#2
Location ID:320066



Photo#1 Production Tanks

Photo#2 Header Valves

Inspection Photos
Location Name: Champlin 248 Amoco C#2
Location ID:320066



Photo#3 Separator



Photo#4 Unused Equipment

Inspection Photos
Location Name: Champlin 248 Amoco C#2
Location ID:320066



Photo#5 **No bullplug**

Photo# Pumpjack and Wellhead

Inspection Photos
Location Name: Champlin 248 Amoco C#2
Location ID:320066



Photo#7 No containment