

Location

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds.		
Corrective Action:	With in the designated setback, remove debris and weeds per Rule 606. Corrective Action Date 12/2/2022. See attached photo # 1 through 4		Date: 12/02/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Shares berm with crude	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.913173,-104.595198

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate

Comment: •Rule 906. Stained soil around load out bucket.	
Corrective Action: Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/9/2022 to remove stained soil. See attached photo # 3.	Date: 12/09/2022

Wells Served By Facilities Above

API Number
001-08898

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 203389 Type: WELL API Number: 001-08898 Status: TA Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: unable to see bradenhead due to weeds

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday, November 7th, 2022 at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: DANMAR P.C. LLC Location name: Cimyotte 6-21 API # 001-08898 Location ID #: 320297 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed:</p> <ul style="list-style-type: none"> • Rule 606: Weeds, dead weeds. With in the designated setback, remove debris and weeds per Rule 606. Corrective Action Date 12/2/2022. See attached photo # 1 through 4. • Rule 906. Stained soil around load out bucket. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/9/2022 to remove stained soil. See attached photo # 3. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/08/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403222318	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908102
700901270	Inspction photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908095