

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2022

Submitted Date:

11/08/2022

Document Number:

702500749**FIELD INSPECTION FORM**Loc ID 334038 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	<a href="#">All SW field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262009	WELL	PR	07/09/2002	CBM	067-08670	DUELL 32-6 5-1	PR
293766	WELL	PR	11/29/2007	CBM	067-09450	DUELL 32-6 5-3	PR
473772	Domestic Tap	AC	03/17/2020		-	Domestic Tap 5NENE	AC
473773	Domestic Tap	AC	03/17/2020		-	Domestic Tap 5NENE	AC

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	2" pipe and valve at wellhead are unused (IMG 04). Electric panel mounts near produced water tanks are not in use (IMG 05).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.		Date: 11/24/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Produced water tanks are enclosed by wire fencing.		
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Flow Line	# 8		
Comment:	2" line from 5-1 wellhead to separator, 3" and 1" line from 3-5 wellhead to separator, 1" gas supply line from separator 3-5 wellhead is not in use and locked out/tagged out, 3" line from separator to gas meter run, 1" line from separator to domestic tap to off location, 2 2" lines from separators to produced water.  3" line stubbed up near gas meter run is not in use and not locked out (IMG 06).		
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.a(3)		Date: 11/09/2022
Type: Bird Protectors	# 4		
Comment:	Separator and produced water tank vent stack are screened.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:			Date:
Type: Bradenhead	# 2		

Comment:	Bradenheads are accessible.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 4			
Comment:	Telemetry, domestic gas tap, chemical container with spill prevention, produced water transfer pump.		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		37.050852,-107.518064
Comment:	2 above ground storage tanks, each with 400 bbl capacity.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	Cone top	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berm height is diminished near metal access stairs (IMG 07 and IMG 08). Berms are not adequately maintained.			
Corrective Action:	Repair/maintain berms or other secondary containment devices per Rule 912.d.(1).			Date: 12/08/2022

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	262009	Type:	WELL	API Number:	067-08670	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	293766	Type:	WELL	API Number:	067-09450	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	473772	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	473773	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	Chemical container spill prevention

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403223192	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908833</a>
702500750	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908829">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908829</a>