

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/09/2022

Document Number:

700704692**FIELD INSPECTION FORM**Loc ID 335525 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299165	WELL	PR	11/22/2009	GW	045-17582	KNAUS 30-04C	PR
299204	WELL	PR	11/22/2009	GW	045-17608	KNAUS 30-04A	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 11/7/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Knaus 19-13, at Location # 335525 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (Lack of stabilization) from previous inspection document # 700702621 has not been completed. Therefore C/A date remains the same.

During this inspection the following compliance issues were observed:

1. Location shows some signs of lack of stabilization from previous inspection has not been completed (C/A date remains 5/31/2021)
 2. Stored farm equipment
 3. Holes in secondary containment
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Stored farm equipment			
Corrective Action:	Remove stored equipment		Date:	11/25/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Plunger Lift	# 2			corrective date
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in a plastic containment		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	250 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient		Inadequate
Comment:	Holes in secondary containment			
Corrective Action:	Install or repair liner material to ensure spill or released materials will be maintained with containment structure.			Date: 12/21/2022

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 299165 Type: WELL API Number: 045-17582 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 299204 Type: WELL API Number: 045-17608 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: 1. Location shows some signs of lack of stabilization from previous inspection has not been completed (C/A date remains 5/31/2021)

Corrective Action: Install or repair required BMPs

Date: 05/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403224584	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5910860
700704696	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5910854