

Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Rule 603.o.(1): Maintained berms around tank(s).				
Corrective Action:	Maintained berms around tank(s). Corrective Action Date 12/14/2022. See attached photo # 2.			Date:	12/14/2022

Wells Served By Facilities Above

AirsID

API Number
001-07391

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201987 Type: WELL API Number: 001-07391 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/23/2021 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday November 10TH at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: KP Kaufmann Location name: Signal Reservoir 1 API # 001-07391 Location ID #: 319952 County: Adams While there, I observed a Temporarily Abandoned well. During this inspection the following possible compliance issues were observed: Rule 603.o.(1): Maintained berms around tank(s). Corrective Action Date 12/14/2022. See attached photo # 2. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/15/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901290	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5917043