

Inspection Photos
Location Name: Champlin 248 Amoco A#3
Location ID:320030



Photo#1 Production Tanks & Produced Water Tank

Photo#2 Separator

Inspection Photos
Location Name: Champlin 248 Amoco A#3
Location ID:320030



Photo#3 Flowline Header

Photo#4 Pumpjack/Wellhead