

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/16/2022

Submitted Date:

11/17/2022

Document Number:

705000045

**FIELD INSPECTION FORM**
 Loc ID 436028 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436024	WELL	PR	11/17/2014	OW	123-38894	BERRY FARMS 32N-8HZ	SI
436025	WELL	PR	01/01/2021	OW	123-38895	BERRY FARMS 31N-8HZ	SI
436026	WELL	PR	11/28/2014	OW	123-38896	BERRY FARMS 31C-8HZ	SI
436027	WELL	SI	05/01/2022	OW	123-38897	BERRY FARMS 32C-8HZ	SI
436065	WELL	PR	01/01/2021	OW	123-38911	BERRY FARMS 30N-8HZ	SI
436576	LOCATION	AC			-	BERRY FARMS FACILITY 8-8HZ	EG

**General Comment:**
 COGCC Engineering Integrity Inspection; Flowline Inspection  
 Photos uploaded

**Inspected Facilities**

Facility ID: <u>436024</u>	Type: <u>WELL</u>	API Number: <u>123-38894</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436025</u>	Type: <u>WELL</u>	API Number: <u>123-38895</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436026</u>	Type: <u>WELL</u>	API Number: <u>123-38896</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436027</u>	Type: <u>WELL</u>	API Number: <u>123-38897</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436065</u>	Type: <u>WELL</u>	API Number: <u>123-38911</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436576</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site      Size: 2"      Material: Carbon Steel  
 Variance:      Age:      Contents:

Integrity Summary

Failures:      Spills:      Repairs Made:  
 Coatings:      H2S:      Cathodic Protection:

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation    ☒ 1102. Operations, Maintenance, and Repair    ☒ 1103. Abandonment

Comment: COGCC Inspector met with Oxy contract personnel on location. The existing Berry Farms 8-8HZ facility is being decommissioned and reconstructed/ upgraded to accommodate (5) HZ SI wells and an additional (8) HZ wells being drilled. All tanks and equipment at facility/ battery have been removed; all on location dump/ process flowlines have been removed. The OLF servicing the (5) SI wells have been disconnected (depressurized) at the wellheads (isolated/ blind flanged OOSLAT) and cut and capped below grade at the east side of the facility location. The flowlines (marked) will be reconnected/ returned to service once the new facility construction is finished/ new wells are completed. In addition, (1) OLF that serviced the Berry #1 (PA/ Sept 2022) well has been removed in entirety. A fenced excavation was observed on location; remediation work to remove impacted soils (historical) is in progress.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403217095 received on 11/04/2022: On November 2, 2022, historical soil impacts were discovered following facility decommissioning operations at the Berry Farms 30 31 32-8HZ O SA facility location. Excavation and assessment activities are ongoing.	maclarej	11/17/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000048	Excavation/ remediation work in progress	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918441</a>
705000049	Well and signage; flowline isolated/ blind flanged	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918442</a>
705000050	OLF flowlines pinflagged; view W to facility	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918443">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918443</a>