

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2022

Submitted Date:

11/14/2022

Document Number:

700704702

FIELD INSPECTION FORM

Loc ID 335147 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286319	WELL	PR	12/31/2006	GW	045-12642	SPECIALTY 12C-28-692	PR
286348	WELL	PR	12/27/2006	GW	045-12645	SPECIALTY 22C-28-692	PR
286349	WELL	PR	01/05/2007	GW	045-12644	SPECIALTY 12A-28-692	PR
286350	WELL	PR	12/28/2006	GW	045-12643	SPECIALTY 22A-28-692	PR
412834	WELL	PR	03/17/2010	GW	045-18650	SPECIALTY 22B-28-692	PR
412835	WELL	PR	03/17/2010	GW	045-18649	SPECIALTY 12D-28-692	PR
412836	WELL	PR	03/17/2010	GW	045-18648	SPECIALTY 22D-28-692	PR
412837	WELL	PR	03/19/2010	GW	045-18647	SPECIALTY 12B-28-692	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 11/10/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Specialty 12C, at Location # 335147 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A's (debris and unmarked dead men) from previous inspection document # 700702990 have been completed. C/A (some lack of stabilization) is still present therefore C/A date remains the same (2/19/2021)

During this inspection the following compliance issues were observed:

1. Location shows some signs of lack of stabilization
Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911		
Corrective Action:			Date: _____

Good Housekeeping:			
	Type DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	286319	Type:	WELL	API Number:	045-12642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	286348	Type:	WELL	API Number:	045-12645	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	286349	Type:	WELL	API Number:	045-12644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	286350	Type:	WELL	API Number:	045-12643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	412834	Type:	WELL	API Number:	045-18650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	412835	Type:	WELL	API Number:	045-18649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	412836	Type:	WELL	API Number:	045-18648	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	412837	Type:	WELL	API Number:	045-18647	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [1. Location shows some signs of lack of stabilization](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 02/19/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403228163	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913941
700704706	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913937