

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2022

Submitted Date:

11/13/2022

Document Number:

688313211**FIELD INSPECTION FORM**Loc ID 412995 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96340Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 106 GLENMOOR LNCity: ENGLEWOOD State: CO Zip: 80113**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
MacLaren, Joe		joe.maclaren@state.co.us	Flowline Inspector
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	All Inspections
Halde, Kerry	(719) 340-0329	haldeoil@hotmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412994	WELL	PR	04/01/2021	OW	073-06384	ALOHA MULA 2	SI

General Comment:

Routine Field Inspection

Gas leak on flowline to battery in pasture was repaired.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	719-340-0329	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Flir survey found flowline gas leak in pasture. Inspector notified Wiepking-Fullerton on 9/29/2022 of finding. GRADE 1 GAS LEAK means a gas leak that ignites or represents an existing or probable hazard to persons or property and requires immediate repair or continuous action until the conditions are no longer hazardous.		
Corrective Action:	Properly report grade 1 gas leaks to comply with Rule 1104.k and/or determine if this was a Grade 1 gas leak after contacting COGCC flowline people. GRADE 1 GAS LEAK means a gas leak that ignites or represents an existing or probable hazard to persons or property and requires immediate repair or continuous action until the conditions are no longer hazardous.	Date:	11/15/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 412994 Type: WELL API Number: 073-06384 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

403133096 42 (MIRU) -00 Notice Type: MIRU
Date&Time: 08/12/2022 08:00 APPROVED 8/11/2022 8/11/2022 WIEPKING-
FULLERTON ENERGY LLC

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688313387	Wiepking-Fullerton Aloha Mula 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5921611