

Inspection Photos

Loc: 325172

Operator: LOGOS OPERATING LLC

Inspection Date: 11/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 1. Facing southeast toward the location and production equipment. The wellsite is located within an oxbow of the Florida River that is prone to flooding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 2. Facing toward the open top tank. There has been round rock placed around the containment. The round rock is pervious and will not prevent flood water from entering underneath the steel containment. Round rock will also be easily displaced as they do not lock in place as well as angular rock. Another solution needs to be implemented.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 3. The steel containment is no constructed per the Operator's SWMP. A 3.5 ft. shovel was placed at the containment for scale.



Photo 4. The steel containment is only about 4 inches below grade. The steel containment is not constructed per the Operator's SWMP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos




Photo 5. Facing toward the open top tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 7. Facing north toward the location. The wellhead cellar was covered to prevent entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 8. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022

Inspection Photos



Photo 9. Facing southeast toward the location. The area of the road shows signs of scouring where flood flows across the road from left to right towards the Florida River.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:325172 | Date: 11/16/2022