

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401919261

Date Received:

01/28/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-779-9398</u>	<u>Sabre.Beebe@bpx.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685305091
Inspection Date: 07/26/2018 FIR Submit Date: 07/27/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326144

Location Name: TINKER 2-9 GU-N34N8W Number: 9NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 9 Twp: 34N Range: 8W Meridian: N
Latitude: 37.227794 Longitude: -107.746855

FACILITY - API Number: 05-067-00 Facility ID: 215941

Facility Name: TINKER 02-09 Number: 1
Qtrqtr: NWSE Sec: 9 Twp: 34N Range: 8W Meridian: N
Latitude: 37.227794 Longitude: -107.746855

CORRECTIVE ACTIONS:

1 CA# 117687

Corrective Action: Remove unused equipment to comply with Rule 603.f. Date: 08/27/2018

Response: CA COMPLETED Date of Completion: 08/16/2018

Operator Comment: Action Completed: The diversion ditch/berm was rebuilt at the base of the slope around equipment. The culvert under the cattle guard was cleaned out and rock armoring was installed at the outlet. BMPs (wattles) were cleaned out along the east side of the location and the old pipe rack was dismantled and removed. 'Grates' were located outside of the perimeter fence and were assumed to be landowners. Miscellaneous trash and debris were removed. See attached photos

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Action Completed: The diversion ditch/berm was rebuilt at the base of the slope around equipment. The culvert under the cattle guard was cleaned out and rock armoring was installed at the outlet. BMPs (wattles) were cleaned out along the east side of the location and the old pipe rack was dismantled and removed. 'Grates' were located outside of the perimeter fence and were assumed to be landowners. Miscellaneous trash and debris were removed. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 1/28/2019 7:39:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401919261	FIR RESOLUTION SUBMITTED
401919280	CA and Comment completion photos

Total Attach: 2 Files