

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	ag panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	fabricated square tubing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	exposed at surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		

Comment: cards indicate current calibration		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment: automation		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.144790,-104.803620
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	75 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares containment with crude tank				
Corrective Action:		Date:		

AirsID

API Number	AirsID
------------	--------

Wells Served By Facilities Above

API Number

123-19910

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 256705 Type: WELL API Number: 123-19910 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/18/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: Water

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 470300 Type: TANK API Number: - Status: AC Insp. Status: SI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 11-22-2022 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: HSR Cannon Federal 5-17A API #05-123-19910 County: Weld Weather: Clear. Location: Dry. While there, I observed a wellsite and tank battery, SI at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	11/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401267	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923442