

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2022

Submitted Date:

11/23/2022

Document Number:

696304576

FIELD INSPECTION FORM

Loc ID 460646 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10780
Name of Operator: BISON OIL & GAS III LLC
Address: 518 17TH STREET SUIT 1800
City: DENVER State: CO Zip: 80202

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ops@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460660	WELL	DG	05/02/2022	LO	123-49498	Tatanka LD 13-660	PR
460661	WELL	DG	05/03/2022	LO	123-49499	Tatanka LD 13-650	PR
460662	WELL	DG	05/01/2022	LO	123-49500	Tatanka LD 13-670	PR
461587	WELL	DG	04/30/2022	LO	123-49602	Tatanka LD 13-685	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Instrumental Air Units		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Electrical and Automation Equipment		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 4			
Comment:	Appear to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Other	# 4			
Comment:	Gas Injection Wellheads		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: VRT	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Compressor	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 16			
Comment:			Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 4			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	OTHER	STEEL AST		40.754440,-103.844030

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>460660</u>	Type:	<u>WELL</u>	API Number:	<u>123-49498</u>	Status:	<u>DG</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>460661</u>	Type:	<u>WELL</u>	API Number:	<u>123-49499</u>	Status:	<u>DG</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>460662</u>	Type:	<u>WELL</u>	API Number:	<u>123-49500</u>	Status:	<u>DG</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>461587</u>	Type:	<u>WELL</u>	API Number:	<u>123-49602</u>	Status:	<u>DG</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Seeding						
Culverts						
Mulching						
Ditches						
Waddles						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection.	petrie	11/23/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304577	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923896