

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2022

Submitted Date:

11/17/2022

Document Number:

697601937**FIELD INSPECTION FORM**Loc ID 327851 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247439	WELL	SI	05/01/2018	GW	123-15236	SHABLE 17-10G	EI
444943	SPILL OR RELEASE	CL	02/01/2017		-	SHABLE 17-10G	EI

General Comment:

This is an environmental inspection for Spill ID 444943 Shable 17-10G. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds overgrown at the location.		
Corrective Action:	Comply with Rule 606.		Date: 11/24/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>247439</u>	Type: <u>WELL</u>	API Number: <u>123-15236</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>444943</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

COGCC Comments

Comment	User	Date
A solar powered air sparge system has been installed and is operational.	ahmadiiaa	11/17/2022
There is no cap/plug on at least one two-inch monitoring well. Please add cap/or plug.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403232817	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5917812
697601938	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5917810