

Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Laramie Energy LLC Gunderson 20-03 Pad sign near location entrance.



Valve can where Spill/Release Point ID #483326 originated from.

Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Flow path along access road.



Flow path into location storm water feature in the northeast corner of the location.

Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Flow path through culvert under access road into sediment traps.



Area where released fluids breached the bank of a storm water diversion ditch.



Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Flow path into field from breach in storm water ditch.

Second area where storm water ditch was breached.

Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Affected field with grader creating a containment berm.



Initial response containment berm and collection area for released fluids.

Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



Buzzard Creek adjacent to affected field. Boom across the creek can be seen in the center of this photo.



Area where released fluids entered Buzzard Creek.



Inspection Photos
Location Name: Gunderson 20-03
Spill/Release Point ID: 483326



View of Buzzard Creek downstream of affected field.



Second area where released fluids entered Buzzard Creek.