

Location

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.962312,-104.971817
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment: _____
 Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT		

Comment: _____
 Corrective Action: _____ Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____
 Other (Capacity) _____
 Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment: _____
 Corrective Action: _____ Date: _____

Wells Served By Facilities Above

API Number
 001-08381

AirsID

API Number AirsID

Venting:

Yes/No	NO		
Comment:	_____		
Corrective Action:	_____		Date: _____

Flaring:

Type	_____		
Comment:	_____		
Corrective Action:	_____		Date: _____

Inspected Facilities

Facility ID: 202975 Type: WELL API Number: 001-08381 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/13/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Routine inspection</u>	<u>finkenbc</u>	<u>12/02/2022</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>700901325</u>	<u>Inspection photos</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5931715</u>