

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2022

Submitted Date:

12/04/2022

Document Number:

706700037

FIELD INSPECTION FORMLoc ID 316968 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 94300

Name of Operator: WARD & SON* ALFRED

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Luke	(970) 324-0060	crumleypumping@gmail.com	
Deranleau, Greg		greg.deranleau@state.co.us	
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233588	WELL	SI	09/01/2022	OW	121-05641	PIERCE 1	SI

General Comment:

Routine Field Inspection, SI

No 2022 Form 17 in COGCC database.

There are stained soil piles could be from previous skim pit remediation as the skim pit cover is still located near piles-remediation project #9291. See also remediation project #17570 that is not closed that may be from when the pit failed and ran into the hayfield below the pit. There is a closed remediation project #14588 related to flowline leak.

Flowline mapped on COGIS but not on related tab on FIR (draft per COGIS).

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Skim pit cover is still present near the stained soil piles (see photo of stained soil piles).		
Corrective Action:	Comply with Rule 606.	Date:	12/19/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heater Treater	# 1	
Comment:	shed, bermed, fix pipe leak (see attached photo)	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	triplex pump	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	electric motor	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: same earth berms as 500 bbl PW tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
121-05654
121-05641
121-05637
121-08119

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 233588 Type: WELL API Number: 121-05641 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 9/1/2022, last reported Form 7 submitted

Corrective Action: _____

Date: _____

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment:	Stained soil piles on plastic on NE cor of pit area. Plastic in poor condition and cows have been in it (not fenced off).			
Corrective Action:	Contact COCGG EPS by 12/19/2022.			Date: _____

Spill/Remediation:

Comment: Stained soil on plastic on NE cor of pit area (see attached photo). Plastic is not intact under piles as cows have been in piles and there was no fencing.

Corrective Action: Contactor COGCC EPS by 12/19/2022. Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass					

Comment: [Erosion at produced water tank battery, see attached photo.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C.](#)

Date: 12/19/2022

Pits: ☒ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: [dry, see attached photos](#)

Corrective Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
706700048	Ward & Son Alfred Pierce 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932188
706700049	Ward & Son Alfred Pierce 1 TB	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932189