

Inspection Photos

API: 043-06122

Operator: JAVERNICK OIL

Inspection Date: 12/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022

Inspection Photos



Photo 1. Facing southeast long the access road. This drainage crossing must have BMP's installed to accommodate seasonal storm event to prevent material from washing out. BMP may include culvert, rip/rap, ect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022

Inspection Photos



Photo 2. Facing toward the tank battery. There is still stained soils at the berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022

Inspection Photos



Photo 3. Facing southeast along the access road. The soils have been pushed out and disturbed and are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022

Inspection Photos



Photo 4. Facing southeast along the fill slope of the pad. The soils have been pushed out and disturbed and are susceptible to erosion. Disturbed soils need to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022

Inspection Photos



Photo 5. The soils have been pushed out and disturbed and are susceptible to erosion. Disturbed soils need to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-0612 | Date: 12/1/2022