

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/17/2022  
Submitted Date:  
12/05/2022  
Document Number:  
706700009

**FIELD INSPECTION FORM**

Loc ID 302966 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
OGCC Operator Number: 55030  
Name of Operator: MCCARTNEY ENGINEERING LLC  
Address: 4251 KIPLING ST STE 575  
City: WHEAT RIDGE State: CO Zip: 80033

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252056	WELL	SI	05/01/2022	GW	125-05105	SEEDORF 1	PA

**General Comment:**  
Cut, Cap and Cover PA Inspection  
Operator cleaned the flowline but it was too cold to pull it.

**Inspected Facilities**

Facility ID: 252056 Type: WELL API Number: 125-05105 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Excell

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: During cut, cap and cover of PA well cement was >20' below ground surface. Well was filled inside and out to cut that is ~6' below ground surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
706700064	McCartney Engineering Seedorf 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5935291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5935291</a>