

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2022

Submitted Date:

11/30/2022

Document Number:

694500529**FIELD INSPECTION FORM**Loc ID 313040 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Carl, Jeffrey		jbrduco@yahoo.com	
		argaliexplorationcompany@g mail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223426	WELL	PR	06/01/2022	GW	081-06792	FEDERAL SANDWASH 2-1	EI

General Comment:

on 11/28/2022 COGCC staff, Kris Neidel Inspected the Fed 2-1 location. This is an Environmental inspection, outstanding Corrective actions from previous inspections remain. Weather was 25 degrees, wet and snowing. The following was observed at the location; one AGT tank that was formerly a partially buried vessel, meter shed, dehy, chemical tank (methanol?). Corrective Action; a Form 27 that documents the removal of two tanks (AGT and partially buried vessel per rule 911, this should be submitted by 12/30/2022. See attached Photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type STORAGE OF SUPL

Comment: old AGT tank was removed from ground and is sitting on location.

Corrective Action: Remove tank

Date: 01/30/2023

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	100 BBLs	STEEL AST		,

Comment: There are no labels on tank.

Corrective Action: Per Rule 605.h.(3), the tank must be labeled per, "U.S. Department of Transportation's Hazardous Materials Regulations".

Date: 12/30/2022

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Location Construction

Location ID: 223426 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective
Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 223426 Type: WELL API Number: 081-06792 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403244826	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5928376
694500530	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5928373