


Peter Phillips A1
COGCC Doc:690203578
Completed 12/5/22
Rutting and erosion repaired along road.



Stormwater directed towards culvert along road and rutting repaired.



Stormwater directed towards culvert crossing road and rutting repaired.



Sediment cleaned up around tank and redirected flow from tank.

