



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type			
Comment:	dead weeds around WH need to be addressed		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: fabricated steel pipe

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Equipment:**

	#				corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	appears to be plumbed to surface				
Corrective Action:				Date:	
Type:	#				
Comment:	See Inspection Doc # 702401296 for related shared facilities and equipment.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	automation				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	

Comment:	See Inspection Doc # 702401296 for related shared facilities and equipment.		
Corrective Action:		Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 206920 Type: WELL API Number: 013-06415 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/19/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 40 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit test results to the COGCC

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 12-7-2022 at approximately 1000 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: Civitas/Extraction                      Location name: Anderson MB 33-6                      API #05-013-06415                      County: Boulder                      Weather: Clear.                      Location: Dry.                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with COGCC rules.</p>	revasr	12/07/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401295	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5937257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5937257</a>