

Construction and Stormwater Inspection

Date: 12/01/2022

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 457136

Inspection Document #: 696105648

Weld County, CO

NWSE Section 14 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ROHN 9-60/14A

Location ID: 457136



Photos 1 & 2. Photos depict trash and debris observed throughout the location during inspection. Photo 1 taken near entrance; Photo 2 taken near sediment trap.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 3. Taken near the western portion of the location, facing north. Photo illustrates tumbleweeds piled up against equipment.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 4. Facing north from topsoil stockpile. Photo illustrates the stockpile has been temporarily stabilized with evidence of drill rows and crimped straw mulch.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 5. Facing south from topsoil stockpile. Photo shows stormwater BMPs (e.g. perimeter ditch and berm, and sediment trap, etc) have been installed during the construction phase of the location.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 6. Facing east from sediment trap, see comments in Photo 5.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 7. Facing west from sediment trap, see comments in Photo 5.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 8. Facing northeast from the southwest corner of location, see comments in Photo 5.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136



Photo 9. Facing south from northwest corner, see comments in Photo 5.

Inspection Photos
Location Name: ROHN 9-60/14A
Location ID: 457136




Photo 10. Taken from the southwest corner of location, facing northeast. Photo illustrates presence of undesirable vegetation (e.g. russian thistle and kochia) in a portion of the interim area of the location. A follow-up interim reclamation inspection will be conducted at a later date to ensure compliance with 1003 Rules.