

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2022

Submitted Date:

12/09/2022

Document Number:

705000084

FIELD INSPECTION FORM

Loc ID 319746 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201246	WELL	SI	08/01/2020	GW	001-06649	SUTTON 41-22	PA
319746	LOCATION	AC	08/01/2020		-	SUTTON-61S65W 22NENE	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photo uploaded](#)

Inspected Facilities

Facility ID: 201246 Type: WELL API Number: 001-06649 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Sutton 41-22) has been plugged and abandoned; cut and cap operations are pending. COGCC form 42 notice of start of plugging operations doc #403146018 received 08/24/2022. COGCC form 42 flowline pre-abandonment notice doc #403131764 received 08/02/2022. No flowline risers observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. An OOS GMR is located on the east side of location. No Civitas personnel were on location at the time of inspection.

Corrective Action: _____ Date: _____

Facility ID: 319746 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403253852 received on 12/08/2022: A historical release was discovered at the Sutton-61S65W 22NENE tank battery during decommission activities. Multiple soil samples were above COGCC standards. Additional information will be provided regarding source removal/remediation activities. Historical impacts were discovered above COGCC standards during tank battery decommissioning. Routine AVO inspections are scheduled for all oil and gas facilities.	maclarej	12/09/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000085	Location signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5939735
705000086	PA well and OOS GMR; view east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5939736