





SITE NAME: Koch Kenneth E A1 O SA							DATE: 12/7/2022		REM. PROJECT #:		WEATHER: 38 Degrees, Sunny	
SITE DIRECTIONS: CO Hwy 52 & CR 3, S 5/10, W Into							CLIENT: Oxy					
LEGALS AND LAT/LONG: 40.079631, -105.038060							TASMAN PERSONNEL: Logan Molson					
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: West					
SOIL SAMPLING							FACILITY INFRASTRUCTURE					
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity			
							Above Ground Storage Tank (AST)		3			
12/7/2022 10:30	PW1-B01@5'	0.4	Organic Content	Organic Odor	Yes	Lab	Buried or Partially Buried Vessel		1			
12/7/2022 10:35	PW1-N01@3'	0.5	No Staining	No Odor	Yes	N/A	Separator		1			
12/7/2022 10:37	PW1-S01@3'	0.2	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)		1			
12/7/2022 10:39	PW1-E01@3'	2.5	No Staining	No Odor	Yes	Lab	Dump Line		1			
12/7/2022 10:41	PW1-W01@3'	0.4	No Staining	No Odor	Yes	N/A	Wellhead					
12/7/2022 13:15	SEP1-B01@3"	1571	No Staining	Strong HC Odor	Yes	Lab	Flowline					
12/7/2022 13:20	SEP1-B02@3"	112.6	No Staining	HC Odor	Yes	Lab	Other:					
12/7/2022 13:30	AST1-B01@3"	0.1	No Staining	No Odor	Yes	N/A	Soil Loads Removed					
12/7/2022 13:32	AST1-B02@3"	0.3	No Staining	No Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?					
12/7/2022 13:34	AST2-B01@3"	0.0	No Staining	No Odor	Yes	N/A	ESTIMATED VOLUME OF IMPACTS:					
12/7/2022 13:36	AST2-B02@3"	0.2	No Staining	No Odor	Yes	Lab	Date		Number		CY	
12/7/2022 13:38	AST3-B01@3"	0.8	No Staining	No Odor	Yes	Lab						
12/7/2022 13:40	AST3-B02@3"	0.6	No Staining	No Odor	Yes	N/A						
12/7/2022 13:42	ECD1-B01@3"	0.4	No Staining	No Odor	Yes	N/A						
12/7/2022 13:45	BG-01@3"	0.1	No Staining	No Odor	Yes	Lab						
12/7/2022 13:50	BG-02@3"	0.0	No Staining	No Odor	Yes	Lab	Total Removed		0		0	
12/7/2022 13:55	BG-03@3"	0.0	No Staining	No Odor	Yes	Lab	Disposal Facility:					
12/7/2022 14:00	BG-04@3'	0.1	No Staining	No Odor	Yes	Lab	Groundwater Recovery					
12/7/2022 14:05	BG-04@6'	0.0	No Staining	No Odor	Yes	Lab	DATE GW ENCOUNTERED:			DEPTH:		
12/7/2022 15:45	MH1-B01@3"	0.7	No Staining	No Odor	Yes	N/A	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?					
							LNAPL OR SHEEN OBSERVED ON GW?					
GROUNDWATER SAMPLING							Date		BBLS			
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?						
							Total Removed		0			
							Disposal Facility:					

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:		
Notes/Conditions: Rain water and snow melt collected around the PWV prior to removal and filled into pit afterward. Pictured water is not groundwater			Notes/Conditions:				

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:		
Notes/Conditions:			Notes/Conditions:				

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Prior sampling location of 3" dug down to expose dump lines for removal			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log




BG-01@3"
X



BG-02@3"
X

Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

 <p>BG-03@3" X</p>			 <p>BG-04@3'&6' X (Backfilled before photo)</p>				
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
		Contents:				Contents:	
Notes/Conditions:				Notes/Conditions:			