

Location			
Lease Road:			
Type	Access		
comment:	walk in no access rd		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	ag panel		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 6		corrective date
Comment:	automation		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		40.154620,-104.848070
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	50 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tank			

Corrective Action:	Date:
--------------------	-------

Wells Served By Facilities Above

AirsID

API Number
123-29706

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 300382 Type: WELL API Number: 123-29706 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, Form 06A doc # 403108165.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 23 Fluid Type: Water

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 12-9-2022 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: Glover V12-31 API #05-123-29706 County: Weld Weather: Clear & cold. Location: Dry. While there, I observed a wellsite and tank battery, SI at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	12/09/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401325	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5939893