

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8557 From entrance to location.



Photo #8558 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8559 From entrance to location.



Photo #8563 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8564 Multiple places with unused equipment.



Photo #8560 Multiple places with unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8565 Stored equipment.



Photo #8566 Stored equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8567 Stored equipment.



Photo #8570 Tank insulation needs repaired.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY FED (MDP PAD #12) /22D-20-691

Location ID: 414522



Photo #8569 PRV leaking Referto OGIS.



Photo #8570 Multiple thief hatches leaking refer to OGIS.