

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU FED (MDP PAD #10) /23A-20-691

Location ID: 417399



Photo #8571 From entrance to location.



Photo #8572 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU FED (MDP PAD #10) /23A-20-691

Location ID: 417399



Photo #8573 From entrance to location.



Photo #8574 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU FED (MDP PAD #10) /23A-20-691

Location ID: 417399



Photo #8576 Unused equipment.



Photo #8577 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU FED (MDP PAD #10) /23A-20-691

Location ID: 417399



Photo #8584 Multiple places with unused equipment.



Photo #8579 Tank label weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU FED (MDP PAD #10) /23A-20-691

Location ID: 417399



Photo #8580 Leaking PRV refer to OGIS.



Photo #8581 Multiple leaking Gauge hatches refer to OGIS