

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334742

Location Name: MILLER-67S93W/14NWNE

Inspection Document #: 702801037

Garfield County, CO

NWNE Section 14 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER-67S93W/14NWNE
Location ID: 334742



Photo 1. Photo taken from the south shows an overview of the location, including interim areas.

Inspection Photos
Location Name: MILLER-67S93W/14NWNE
Location ID: 334742



Photo 2. Photo shows production areas. Piping is open ended/uncapped allowing for wildlife access.



Inspection Photos

Location Name: MILLER-67S93W/14NWNE

Location ID: 334742



Photo 3. Photos show production areas and an excavation at separators. Excavated soil is surrounded by a berm of loose, unconsolidated soil. Orange safety fence is in disrepair/not properly installed to exclude entry into trench.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801037

Inspection Photos
Location Name: MILLER-67S93W/14NWNE
Location ID: 334742



Photo 4. Photos an excavation at well API #045-10247. Excavated soil is surrounded by a berm of loose, unconsolidated soil. Orange safety fence is in disrepair/not properly installed to exclude entry into trench.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801037

Inspection Photos
Location Name: MILLER-67S93W/14NWNE
Location ID: 334742



Photo 5. Photos show interim areas to the north (left) and south (right) appear dominated by introduced perennial grasses.

