

Inspection Photos

API: 071-08113

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/12/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 1. Facing west at the beginning of the access road. Stormwater is flowing around the rock check dam at the red arrow and is in need of maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 2. Facing northwest along the access road. The rock check dams have filled in with sediment and are in need of maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 3. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 4. Facing west toward the well and pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 5. Facing toward the pit. The pit is shallow; less than 2 ft. deep and needs to be constructed to allow 2 ft. freeboard. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022

Inspection Photos



Photo 6. The freeboard marker is not is not 2ft. In length and does not show the vertical depth where it is installed. (Lays horizontal on the ground)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: `12/12/2022