

Inspection Photos

API: 071-09079

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 1. Facing southeast toward the Longs Canyon drainage crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 2. Facing southeast along the main road. Recent work has been performed along the road. Disturbed areas have been seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 3. This culvert outlet along the road has been cleaned out and soils were seeded. Outlet protection should be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 4. This culvert along the road has been cleaned out however the damage portion needs to be cut off so it doesn't plug up with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 5. The culverts along the access road have recently been cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 6. Facing northeast along the access road. Repairs have recently been performed along the road. The check dam is not sufficiently installed and more BMP's are needed in this area. Does not appears disturbed soils were seeded.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022

Inspection Photos



Photo 7. Facing west toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09079 | Date: 12/12/2022