

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2022

Submitted Date:

12/15/2022

Document Number:

700300482**FIELD INSPECTION FORM**Loc ID 320852 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	Owner

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205239	WELL	PR	02/01/2020	OW	007-06117	NIELSEN 4	PR

**General Comment:**

Takj battery and berm construction now complaint with floodplain rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	emergency services and 24 hour contact 3's present on sign	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type			
Comment:	gearbox leak no longer present, CA from previous inspection performed		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	shares engineered floodplain berms with both tanks for Albert Martinez 1				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Significantly modified berms should be able to contain 150% of largest vessel. Signifiscant backfill soil material inside berms taking up some capacity.				
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**Facility ID: 205239 Type: WELL API Number: 007-06117 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 12/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Bradenhead access not oresent/visible although test submitted, no variance due to well construction in well file.Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)

Date: \_\_\_\_\_

**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Light Speed: 1-3 (mph) Direction From: SW Weather: Clear Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM

Equipment
Oil Tank(s)
Wellhead(s)

Comment: wellhead appears tight, just detectable under normal sensitivity leak at valve observed

Corrective

Date:

Action:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300536	well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945715</a>
700300537	wellhead, no visible bradenhead access	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945716</a>
700300538	engineered metal tsank berms	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945717</a>
700300539	battery sign and tank labels and berms	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945718</a>
700300540	wellhead FLIR, leaking valve	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5945719</a>