

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2022

Submitted Date:

12/16/2022

Document Number:

705000094**FIELD INSPECTION FORM**Loc ID 336528 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296725	WELL	PA	12/19/2019	GW	123-26884	BULTHAUP 39-6	PA
296726	WELL	SI	12/01/2021	GW	123-26885	BULTHAUP 16-6	PA
336528	LOCATION	AC			-	BULTHAUP-61N68W 6SESE	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 296725 Type: WELL API Number: 123-26884 Status: PA Insp. Status: PAFacility ID: 296726 Type: WELL API Number: 123-26885 Status: SI Insp. Status: PA**Flowline**

#1 Type: Non-Well Site of Lines

Flowline DescriptionFlowline Type: Non-Well Site Size: 2" Material: Carbon Steel
Variance: Age: Contents:Integrity SummaryFailures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. AbandonmentComment: Well (Bulthap 16-6) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403190706 received 10/06/2022. COGCC form 42 notice of flowline abandonment completed doc #403251806 received on 12/06/2022. The wellhead flowline (OLF) has been removed. The facility/ tank battery is being decommissioned; tanks and equipment being removed.

Corrective Action:

Date:

Facility ID: 336528 Type: LOCATION API Number: - Status: AC Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000095	PA well and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5949020
705000096	OLF alignment/ removed; view N toward battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5949021