



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Prime Mover		# 1		
Comment:	gas motor			
Corrective Action:				Date:
Bird Protectors		# 1		
Comment:				
Corrective Action:				Date:
Deadman # & Marked		# 4		
Comment:				
Corrective Action:				Date:
Pump Jack		# 1		
Comment:				
Corrective Action:				Date:
Bradenhead		# 1		
Comment:	plumbed to surface			
Corrective Action:				Date:

**Tanks and Birms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:	70 BBL				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Birms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:		shares containment with oil tank			Date:	
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:					Date:	
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:					Date:	
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:					Date:	
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:					Date:	
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 202904 Type: WELL API Number: 001-08309 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, cold, windy.	medinaj	12/05/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504330	Inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950840">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950840</a>