

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/13/2022

Submitted Date:

12/19/2022

Document Number:

697601988

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Ahmadian, Alexander On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Meis, Craig		cmeis@kpk.com	<a href="#">KPK Environmental</a>
-, Marcom		primarycontractor@marcomllc.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475199	OFF-LOCATION FLOWLINE	AC	01/13/2021		-	Wellhead Line 25SWSW	EI

**General Comment:**

COGCC contract personnel was onsite witnessing sampling that is proceeding under Spill ID 483322 with a forthcoming Form 27. Any corrective actions from previous inspections that have not been addressed are still applicable.

[Photos attached to document site conditions.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Fencing around the excavation is adequate.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Gate with passcode is required to enter due to the occupied structures located near the spill.		
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 475199 Type: OFF- API Number: - Status: AC Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Other	Adequate		
Comment	No oily waste is being stockpiled. All oily waste is being placed into dump trucks and hauled offsite immediately.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	COGCC contract personnel was at location witnessing the sampling of the spill excavation. Excavation is 42'x 40'x 12' Groundwater with no sheen was observed at approximately 12'. Excavation is ongoing as of the site inspection.			
Corrective Action:				Date: _____

Emission Control Burner (ECB):	_____			
Comment:	_____			
Pilot:	Wildlife Protection Devices (fired vessels): _____			

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601989	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951117</a>