



Doc# 1311066

EnviroScan - DNR, OGCC <dnr\_ogcc.enviroscan@state.co.us>

Fwd: [EXTERNAL]Fwd: Site Inspection Request

1 message

Graber - DNR, Nikki <nikki.graber@state.co.us> Mon, Dec 19, 2022 at 8:09 AM  
To: OGCC EnviroScan - DNR <dnr\_ogcc.enviroscan@state.co.us>

Please upload correspondence and site photos to Remediation #15825

Thank you.

Nikki Graber, P.G.  
DJ Basin Region Environmental Supervisor



C 970-250-0543  
O 970-663-5719  
[1120 Lincoln Street, Suite 801, Denver, CO 80203](#)  
[nikki.graber@state.co.us](mailto:nikki.graber@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

----- Forwarded message -----  
From: **Craig Meis** <[cmeis@kpk.com](mailto:cmeis@kpk.com)>  
Date: Fri, Dec 9, 2022 at 3:48 PM  
Subject: RE: [EXTERNAL]Fwd: Site Inspection Request  
To: Maclaren - DNR, Joe <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>  
Cc: Schlagenhauf - DNR, Mark <[mark.schlagenhauf@state.co.us](mailto:mark.schlagenhauf@state.co.us)>, [nikki.graber@state.co.us](mailto:nikki.graber@state.co.us) <[nikki.graber@state.co.us](mailto:nikki.graber@state.co.us)>, Jeff Petersen <[JPetersen@kpk.com](mailto:JPetersen@kpk.com)>

Good Afternoon Joe

Went out to the Coslet #3 site this morning and wanted to share photos from my visit along with additional information shared by Jeff Peterson. Attached are the photos from this morning. The first photo in the attached, I'm looking down on the pipes into the excavation to avoid taking a photo into the sun as was shared with us yesterday. The two other photos are just close ups of either end where the cut/cap were completed. As you can see, both the 1-1/2" PVC abandoned supply gas line and the 3" Fiberglass flowline were cut and capped yesterday. The crews applied heat packs to the fiberglass fittings to cure the epoxy for the Victaulic end cap. As indicated previously, the source of the surfacing staining was from the 1-1/2" PVC abandoned supply gas line shown in the Apex photo but was not visible once crews arrived. My guess is dirty water that may have accumulated in the abandoned supply gas line that spilled out when disturbed or overfilled. Let me know if any additional questions and appreciate you raising this to my attention.

Have a good weekend

Craig

**From:** Craig Meis  
**Sent:** Thursday, December 8, 2022 3:16 PM  
**To:** Maclaren - DNR, Joe <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>  
**Cc:** Schlagenhauf - DNR, Mark <[mark.schlagenhauf@state.co.us](mailto:mark.schlagenhauf@state.co.us)>; [nikki.graber@state.co.us](mailto:nikki.graber@state.co.us)  
**Subject:** RE: [EXTERNAL]Fwd: Site Inspection Request

Joe

Just received these photos from Jeff Peterson via text per his response and actions at the site following our receipt of your email. From the photo taken by Apex below on 11/28/22, the surface staining is coming from an abandoned dry gas line and there was no visible staining when the crew arrived on site to respond today. The fiberglass line in the attached photos is the flowline and the pvc pipe is an abandoned supply gas line when the pumping units operated on natural gas. I'll provide some more information as Jeff shares with me as he is still doing some investigation into this matter. Just wanted to make sure you knew we did get out there today to respond. I plan to be in the field for part of the day tomorrow and will plan to go by and take some better photos to share than what has been attached along with any additional information.

More to come

Thanks

Craig

**From:** Craig Meis  
**Sent:** Thursday, December 8, 2022 10:49 AM  
**To:** Maclaren - DNR, Joe <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>  
**Cc:** Schlagenhauf - DNR, Mark <[mark.schlagenhauf@state.co.us](mailto:mark.schlagenhauf@state.co.us)>  
**Subject:** RE: [EXTERNAL]Fwd: Site Inspection Request

Thanks Joe

Will get out there right away to investigate.

**From:** Maclaren - DNR, Joe <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>  
**Sent:** Thursday, December 8, 2022 10:46 AM  
**To:** Craig Meis <[cmeis@kpk.com](mailto:cmeis@kpk.com)>  
**Cc:** Schlagenhauf - DNR, Mark <[mark.schlagenhauf@state.co.us](mailto:mark.schlagenhauf@state.co.us)>  
**Subject:** [EXTERNAL]Fwd: Site Inspection Request

**Please be cautious:** KPK External Sender Notice: This email is from an external sender. Please take care when clicking links or opening attachments. When in doubt, contact your IT Department

Hi Craig,

Nikki brought this to my attention and I thought I would forward it to you (and Mark). Let me know if you have any questions. Joe

--

Joe MacLaren

Integrity Inspector

Eastern Slope



C 970-382-1680

[1120 Lincoln Street, Suite 801, Denver, CO 80203](#)

[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

----- Forwarded message -----  
From: Graber - DNR, Nikki <[nikki.graber@state.co.us](mailto:nikki.graber@state.co.us)>  
Date: Thu, Dec 8, 2022 at 8:36 AM  
Subject: Site Inspection Request  
To: Joe MacLaren <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>

Joe,

Can you take a look at the KPK Cosslet #3 (Spill ID 474780). Our contractors at Apex noticed a leaking pipe during a recent inspection. See photos below:



Nikki Graber, P.G.  
DJ Basin Region Environmental Supervisor



C 970-250-0543  
O 970-663-5719  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[nikki.graber@state.co.us](mailto:nikki.graber@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

 **Cosllett 3 Photolog.pdf**  
1392K