

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2022

Submitted Date:

12/20/2022

Document Number:

705000097

## FIELD INSPECTION FORM

 Loc ID 336466 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-
**Findings:**
 2 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |
|                    |       | COGCCInspections@Oxy.com      |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 296722      | WELL | SI     | 02/01/2021  | OW         | 123-26881 | BULTHAUP 1-6  | PA          |
| 296723      | WELL | SI     | 04/01/2021  | OW         | 123-26882 | BULTHAUP 27-6 | PA          |

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 296722 Type: WELL API Number: 123-26881 Status: SI Insp. Status: PA

Facility ID: 296723 Type: WELL API Number: 123-26882 Status: SI Insp. Status: PA

**Flowline**

|    |                     |          |
|----|---------------------|----------|
| #1 | Type: Non-Well Site | of Lines |
|----|---------------------|----------|

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Wells (Bulthaupt 1-6, 27-6 ) have been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notices of start of plugging operations received 09/2022. Oxy contract personnel are in the process of pulling/ removing off location flowlines; this work has been initiated at the wellheads and moving south toward facility/ battery. Open bellhole excavations were observed; flowline pipe is being pulled out of the ground between excavations. The facility/ tank battery has been decommissioned; tanks and equipment removed. No Oxy personnel were on location at the time of inspection.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                  | URL   |
|--------------|--|---|
| 705000100    | PA well and signage; FL removal operations   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952331</a> |
| 705000101    | Bellhole excavations; flowline (OLF) removal | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952332">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952332</a> |