

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2022

Submitted Date:

12/20/2022

Document Number:

701103655**FIELD INSPECTION FORM**Loc ID 426403 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatr@scoutep.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Sanford, Anita	(970) 675-3842	Anita.Sanford@scoutep.com	All Inspections
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481872	Flowline System	AC	03/31/2022		-	PRODUCED WATER INJECTION	AC

**General Comment:**

Inspection in response to Form 19 doc# 403257072 Flowline failure

**Inspected Facilities**Facility ID: 481872 Type: Flowline API Number: - Status: AC Insp. Status: AC**Flowline**

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type:                      Size: 3"                      Material: Fiberglass  
 Variance:                      Age:                      Contents: Produced Water

Integrity Summary

Failures: Damage/Defects                      Spills: Yes                      Repairs Made:  
 Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: Line failure leading to a spill. Spill controled and free fluids removed. Flowline has been cut and to be replaced with stainless steel. Tentative planned pressure test on Thursday 12/22/2022.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103656	Flowline integrity inspection 701103655 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5952744</a>