

Inspection Photos
Location Name: Florence # 33-1
Location ID:322229



Photo 1 TNK BTRY No battery sign, No NFPA placards on two tanks



Photo 2 unused equipment: valves open on bottom of tank and tank not connected to any flow line

Inspection Photos
Location Name: Florence # 33-1
Location ID:322229



Photo 3 unused equipment: cattle panels in crude oil containment area



Photo 4 PU

Inspection Photos
Location Name: Florence # 33-1
Location ID:322229



Photo 5 Unused equipment cattle panel on ground



Photo 6 Trash and unused tank on location.

Inspection Photos
Location Name: Florence # 33-1
Location ID:322229



Photo 7 loc pic