

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2022

Submitted Date:

12/21/2022

Document Number:

699805362**FIELD INSPECTION FORM**Loc ID 335331 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262889	WELL	PR	06/27/2002	OW	045-08066	PA 322-34	PR
276064	WELL	PR	07/08/2005	GW	045-10418	PA 522-34	PR
276070	WELL	PR	08/29/2005	GW	045-10419	PA 422-34	PR

General Comment:[COGCC Inspection Report Summary](#)

On 12/20/22 at approximately 15:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PA-66S95W /34SENW.
Location #335331 in Garfield County Colorado
While there, I observed normal production operations.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 3	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 262889	Type: WELL	API Number: 045-08066	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 276064	Type: WELL	API Number: 045-10418	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 276070	Type: WELL	API Number: 045-10419	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Sediment Traps				
Gravel						
Compaction						
		Berms				
		Ditches				
		Gravel				
		Compaction				
		Culverts				
Sediment Traps						
Berms						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for comments.	depaoloc	12/21/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805363	Photos for Insp. #699805362	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5954645