

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2022

Submitted Date:

12/21/2022

Document Number:

694100054**FIELD INSPECTION FORM**Loc ID 307116 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****General Comment:**

This is an environmental inspection for Locatin ID 307116 Magpie 1-A. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: No sign at access road.Corrective Action: Install sign to comply with Rule 605.a.Date: 01/04/2023Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: NoComment: No active spill☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	<u>Open excavation near separator has damaged orange construction fencing that needs to be fixed and/or replaced.</u>		
Corrective Action:	<u>Comply with the fencing requirements per the 1002a rules</u>		Date: <u>12/28/2022</u>

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	<u>Both separator and tank battery have earthen berms that are damaged. Need to be fixed to prevent potential overflow. Use for crude, condensate and produced water. Inadequate berms around tank(s).</u>			
Corrective Action:	<u>Repair or install berms or other secondary containment devices per Rule 912.d.(1).</u>			Date: <u>12/25/2022</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____		
Comment:	<div>No spill present.</div>				
Corrective Action:	<div></div>		Date:	_____	
Reportable:	_____	GPS: Lat	_____	Long	_____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____		

Water Well Complaint:

			Lat	Long	
DWR Receipt Num:	_____	Owner Name:	_____	GPS :	_____

Field Parameters:

Sample Location:	_____	Comment:	_____
------------------	-------	----------	-------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100055	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5954868