

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2022

Submitted Date:

12/22/2022

Document Number:

705000098

FIELD INSPECTION FORM

 Loc ID 460724 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-
Findings:
 2 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
336524	LOCATION	CL			-	BULTHAUP-61N68W 6SENE	EG

General Comment:
 COGCC Engineering Integrity Inspection; Flowline Inspection
 Photos uploaded

Inspected Facilities

Facility ID: 336524 Type: LOCATION API Number: - Status: CL Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: All associated wells being serviced by this facility have been plugged and abandoned. On location dump and process flowlines are being removed. Off location flowlines between area (PA) wells and facility/ battery are being removed/ AIP. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. Fenced excavations were observed on location at battery/ equipment areas. (2) flowlines (2" CS OLF WH lines) were observed in a large excavation at center of location. The flowline cut ends are bullplugged; these flowlines are in process of removal/ AIP. Oxy contract personnel were in the process of removing OLF pipe north of the battery area (OLF's serviced Bulthup 1-6, 27-6 wells). Remediation work at facility/ battery is in progress (historical).

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000102	Signage on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5956949
705000103	Fenced excavation and flowlines exposed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5956950
705000104	Excavations and OOS GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5956951