

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2022

Submitted Date:

12/23/2022

Document Number:

705000105

FIELD INSPECTION FORM

Loc ID 310733 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296721	WELL	SI	04/01/2021	GW	123-26880	BULTHAUP 17-6	PA
310733	LOCATION	AC			-	BULTHAUP-61N68W 6SWNE	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 296721 Type: WELL API Number: 123-26880 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Bulthap 17-6) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403180349 received 09/28/2022. The wellhead flowline (OLF) abandonment/ removal is in progress; (1) flowline/ riser observed at the (PA) well area. The facility/ battery has been decommissioned; tanks and equipment removed. Fenced excavations were observed at the PA wellhead and facility/ battery areas; remediation work is in progress (historical). No Oxy personnel were on location at the time of inspection.

Corrective Action:

Date:

Facility ID: 310733 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000106	Sigange at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5958178
705000107	PA well and signage; 2" CS flowline riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5958179