

# Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327499

Inspection Document #: 701900648

SENW Section 28 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**CO L O R A D O**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 1.** 2021 aerial imagery of the well pad and tank battery. Could not identify well pad access road from historical imagery.

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 2.** Overview photo of the well pad taken at ground level.

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent crop reference area (see photo 5).

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 5.** Well pad reference area.



Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 6.** Overview photo of the tank battery taken at ground level from the western edge facing northeast. Note: tank battery access point remains with gravel.

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 7.** Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Keiser 22-28  
Location ID: 327499



**Photo 8.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west.