

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403207780

Date Received:
10/27/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beardslee, Tom</u>	<u>970-420-3935</u>	<u>tom.beardslee@state.co.us</u>
<u>Javernick, James</u>	<u>719-671-3787</u>	<u>javernick1@gmail.com</u>
<u>Kosola, Jason</u>	<u>719-641-0291</u>	<u>jason.kosola@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 707900076

Inspection Date: 10/19/2022

FIR Submit Date: 10/19/2022

FIR Status: _____

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322233

Location Name: DRAPER-620S69W Number: 22SWNW County: FREMONT

Qtrqr: SWN Sec: 22 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.296950 Longitude: -105.104190

FACILITY - API Number: 05-043-00 Facility ID: 291241

Facility Name: DRAPER Number: 2

Qtrqr: SWN Sec: 22 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.296950 Longitude: -105.104190

CORRECTIVE ACTIONS:

1 CA# 165523

Corrective Action: Comply with rule 606

Date: 11/19/2022

Response: CA COMPLETED

Date of Completion: 10/24/2022

Picked up 2" steel pipe and piece of 1" poly pipe and removed off location.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator corrective actions appears to have been completed. See inspection Doc# 707900398.

2 CA# 165524

Corrective Action: Comply with rule 606

Date: 11/19/2022

Response: CA COMPLETED

Date of Completion: 10/26/2022

Operator Comment: CA REVIEW REQUEST DATE: 10/26/22: Requesting delay. Recently routed production to a common tank with two other wells and have kept this tank available to be used if bypass to common tank is necessary.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator corrective actions appears to have been completed. See inspection Doc# 707900398.

3 CA# 165525

Corrective Action: Immediately cease venting/flaring per rule 903 d (2)

Date: 10/20/2022

Response: CA COMPLETED

Date of Completion: 10/20/2022

Operator Comment: Received Field inspection report (FIR, Doc # 707000076, via email on 10/20/22 at 1:14 AM. Upon review of emails at start of workday, 7-7:30 am, Operator immediately dispatched pumper to the Draper #2 well to inspect valves, pipes, fittings and ensure good mechanical integrity and then placed valve in closed position to cease venting from the well.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator corrective actions appears to have been completed. See inspection Doc# 707900398.

4 CA# 165526

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS 905 e

Date: 11/19/2022

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: CA COMPLETION DATE: 10/25/22: Operator removed oily dirt from around wellhead and tank load-out and replaced with clean soil.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator corrective actions appears to have been completed. See inspection Doc# 707900398.

5 CA# 165527

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/19/2022

Response: CA COMPLETED

Date of Completion: 10/20/2021

Operator Comment: CA COMPLETION DATE: 10/20/22: Operator repaired leaking flow line off well head. Inspected and made sure all valves, pipes and fittings were in good mechanical condition.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator corrective actions appears to have been completed. See inspection Doc# 707900398.

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has completed 4 of 5 corrective actions and has requested a review of 1 of 5 corrective actions (delay removal of unused tank and allow to be used as a by-pass tank, as necessary.
Note: Jason Kosola inspection on 10/25/22, doc. #700600425, also identifies these specific corrective actions completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Javernick

Signed: _____

Title: Owner

Date: 10/27/2022 2:29:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403207780	FIR RESOLUTION SUBMITTED
403210810	Post corrective action photos

Total Attach: 2 Files