

Inspection Photos

API: 071-08606

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/28/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 1. Facing west along the main road in Jaroso Canyon. This low area of the road accumulates the intermittent stream water and needs to be built up and stabilized. Approx. Lat/Long:37.29289,-104.84867.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 2. Facing southeast along the road. Stormwater is accumulating on the road and vehicles are driving around this area causing widening of the road. Approx. Lat/Long:37.29215,-104.84876.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 3. Further up the road there is vehicle rutting of the road. Soils are frozen so repairs will likely need to be made at a later in the season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 4. Facing northwest along the main road. The rock check dams are in need of maintenance. Lat/Long:37.28628,-104.85538.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 5. Facing north at the TA wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022

Inspection Photos



Photo 6. Facing west at the location. There is also culverts further along the road that are filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08606 | Date: 12/28/2022