

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2022

Submitted Date:

12/29/2022

Document Number:

702801090**FIELD INSPECTION FORM**Loc ID 334613 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | COGCC.inspections@caerus<br>oilandgas.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num | Facility Name             | Insp Status |
|-------------|----------|--------|-------------|------------|---------|---------------------------|-------------|
| 334613      | LOCATION | AC     |             |            | -       | SHIDELER-67S93W<br>25NWSW | RI          |

**General Comment:**

On 12/27/2022, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at Caerus Piceance LLC's SHIDELER-67S93W/25NWSW Location #334613 in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Tank battery sign absent
- Open ended piping at tank battery and separators
- Bull plugs not installed on tank drains

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | BATTERY                                 |       |            |
| Comment:             | Sign not posted at battery.             |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.e. | Date: | 02/27/2023 |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

|                           |  |  |                  |
|---------------------------|--|--|------------------|
| <b>Good Housekeeping:</b> |  |  |                  |
| Type                      | OTHER  |  |                  |
| Comment:                  | Open ended piping at tank battery. No control measures to prevent wildlife entry observed. |  |                  |
| Corrective Action:        | Eliminate possibility of wildlife to enter open lines.                                     |  | Date: 01/08/2023 |
| Type                      | OTHER  |  |                  |
| Comment:                  | Bull plugs not installed on tank drains.   |  |                  |
| Corrective Action:        | Install bull plugs.  |  | Date: 01/08/2023 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| Inspected Facilities |        |       |          |             |   |         |    |               |    |
|----------------------|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID:         | 334613 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment No anchors observed.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|   |   |
|---|---|
| Date Final Reclamation Started: _____                         | Date Final Reclamation Completed: _____         |
| Final Land Use: _____   |   |
| Reminder: _____   |   |
| Comment: _____  | _____   |
| Well plugged _____  | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____  | No disturbance /Location never built _____      |
| Access Roads _____  | Regraded _____                                  |
| _____   | Contoured _____                                 |
| Gravel removed _____  | Culverts removed _____                          |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____                                  | Dust and erosion control _____                  |
| Non cropland: Revegetated 80% _____                           | Cropland: perennial forage _____                |
| Weeds present _____   | Subsidence _____                                |
| 1004.d. FINAL VEGETATION TRANSECT                             |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____                     |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____                     |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____                   |   |
| VEGETATIVE COVER _____  |   |
| Comment: _____  | _____   |

|   |   |
|---|---|
| Corrective Action: <input style="width: 90%;" type="text"/> | Date: <input style="width: 90%;" type="text"/>  |
| Overall Final Reclamation <input type="checkbox"/>          | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment: No stormwater issues observed in visible portions of the location. Location and access road are frozen and snow covered at the time of this inspection; unable to perform full stormwater inspection.

Corrective Action:

Date:

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403275703    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964562</a> |
| 702801091    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964554">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964554</a> |