

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2023

Submitted Date:

01/05/2023

Document Number:

697601998

FIELD INSPECTION FORM

Loc ID 310312 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		NBL_DJBU_Inspections@NBLENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292016	WELL	SI	07/01/2022	GW	123-26212	LIBSACK 4-8-27	EI
473658	OFF-LOCATION FLOWLINE	AC	03/25/2021		-	Wellhead Line 27SWSE	EI
482474	SPILL OR RELEASE	CL	08/16/2022		-	Libsack Vent Line Spill	EI
483142	SPILL OR RELEASE	AC	10/28/2022		-	Historical: Libsack 4-8-27	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: Emergency signage is adequate. Other miscellaneous signage is beginning to fade and is difficult to read.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: Chainlink fencing with barbed wire on top is surrounding the tank battery and is adequate.

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE			STEEL AST		

Comment: Above ground storage tank is in good condition with adequate signage.

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: berm surrounding tank battery is adequate.

Corrective Action:

Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER					

Comment: Produced water vault is in good condition.

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 292016 Type: WELL API Number: 123-26212 Status: SI Insp. Status: EI

Facility ID: 473658 Type: OFF- API Number: - Status: AC Insp. Status: EI

Facility ID: 482474 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 483142 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601999	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5971787