

Final Reclamation and Stormwater Inspection

Date: 12/28/2022

Operator: CHAMPLIN PETROLEUM COMPANY
(15550)/ ANADARKO E&P ONSHORE LLC (2800)

Location ID: 454039

Inspection Document #: 696105670

Morgan County, CO

SESE Section 29 T2N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bower Water Plant
Location ID: 454039



Photo 1. Facing northeast from the western portion of the location. Water plant pictured.

Inspection Photos
Location Name: Bower Water Plant
Location ID: 454039



Photo 2. Facing east from the western portion of the location. Flowlines pictured.

Inspection Photos
Location Name: Bower Water Plant
Location ID: 454039



Photo 3. Facing west from the western portion of the location. Valve box pictured.

Inspection Photos
Location Name: Bower Water Plant
Location ID: 454039



Photo 4. Facing east from the water plant. Foundation and all equipment will need to be removed.

Inspection Photos
Location Name: Bower Water Plant
Location ID: 454039



Photo 5. Facing east from the eastern portion of the location. Various fiberglass and steel pipe observed.