

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2023

Submitted Date:

01/06/2023

Document Number:

705000122

FIELD INSPECTION FORM

Loc ID 320533 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278915	WELL	SI	08/01/2020	GW	001-09547	COLLINS HH 20-3J	PA
460738	Location	AC			-	COLLINS HH-61S65W 20NENW	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 278915 Type: WELL API Number: 001-09547 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Collins HH 20-3J) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403215945 received 11/01/2022. No flowlines/ risers observed at the (PA) wellhead or facility/ battery areas. Bellhole excavations (fenced) were observed between the PA well and battery where FL pipe was pulled/ removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. An OOS GMR is located on the south side of location. No Civitas personnel were on location at the time of inspection.

Corrective Action:

Date:

Facility ID: 460738 Type: Location API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403275845 received on 12/30/2022: Historical impacts were discovered during decommissioning of the Collins HH-61S65W 20NENW tank battery. Historical impacts were discovered during decommission in the vicinity of the separator.	maclarej	01/06/2023
As outlined on COGCC form 19 spill report Doc #403276210 received on 12/30/2022: Historical impacts were discovered during decommissioning of the Collins HH20-3J FL at the separator and wellhead locations. Soil samples exceeded COGCC standards. Historical impacts were discovered during decommission activities. Routine AVO inspections are scheduled at all oil and gas facilities.	maclarej	01/06/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000127	Location signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972920
705000128	Bellhole excavations OLF removed; OOS GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972921